



Oxy USA, WTP, LP  
Rockies RMT – Mid-Continent Business Unit  
Grand Junction, Colorado  
WELL WORKOVER PROCEDURE

**CC 697-15-22D**

**Project number: 1139934**

**Objective:** Plug and Abandon Well

The safety of the crew, company representative, and protection of the environment is top priority. If any member of Oxy, the Service Company, or a third party observer feels that the work is being performed in an unsafe manner, shut the job down and discuss what needs to be done to safely perform the needed tasks. If needed, shut down the work until an Oxy supervisor can be consulted even if operations need to be deferred until another day.

**Engineer:** Sanaz Seddighrad; Cell – (281) 740-2956

**Well Data**

**Note:** During drilling operations, when surface casing was set (2913') in 2006, the parasite string parted and the well was temporarily abandoned with a plate welded on the surface after the well was cemented.

**Surface Casing @ 2913'    Casing: Size: 9.625"                      Weight:36 PPF                      Grade: J-55**

**Procedure:**

1. Remove the cover.
2. Bleed down pressure off the plate. Perform LEL test. Set up fire watch.
3. Cut off welded plate.
4. Fill with fresh water to within 20' of surface.
5. Push cement plug to 20'
6. Cement with 8.6 cu ft of Redimix to surface.
7. Cut off pipe within 4 ft of surface and weld on cover plate.