

WORKOVER PROCEDURE

WELL NAME: UPV 31-02G3 DATE: 8/3/2012

LOCATION: Qtr/Qtr: NWNE Section: 31 Township: 6N Range: 63W

COUNTY: WELD STATE: CO API #: 05-123-18977

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 20# @ 453' KB Elevation: 4642'
Surface Cmt: 200 sx cement to surface GL Elevation: 4628'
Long St Csg: 3 1/2" 7.7# @ 6953' TD: 6971'
Long St Cmt: 100 sx TOC @ 5552' PBTD: 6869'
Long St Date: 8/21/1995

Plug Back (Sand or CIBP):
Perforation Interval (1): Fort Hays 6749' - 6765'
Perforation Interval (2): Codell 6765' - 6776'
Perforation Interval (3):
Tubing: 2 1/16" 3.25# J-55 @ 6729' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 1/16" tubing. And lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6650', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 5350'. POOH with casing laying down on trailer.
5) RIH w/ workstring to 5350' Pump 50 sx stub plug. Wait 4 hrs, tag plug.
6) Pump 40 sx courtesy plug @2500'. POOH w/workstring to 550'. Pump approx 250 sx shoe plug, cement to surface
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.