

WORKOVER PROCEDURE

WELL NAME: LOUSTALET B 15-14 DATE: 8/9/2012
LOCATION: Qtr/Qtr: SESW Section: 15 Township: 5N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-15013

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 341' KB Elevation: 4584'
Surface Cmt: 300 sx GL Elevation: 4574'
Long St Csg: 2 7/8" 6.5# @ 6874' TD: 6895'
Long St Cmt: 325 sx TOC @ 5930' PBTD: 6846'
Long St Date: 7/11/1991, csg repair 8/19/1998

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perfs 6804' - 6816'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1 1/4" J-55 2.33# tbg @ 6780' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/1 1/4" tubing. And lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6700', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 5800'. POOH with casing laying down on trailer.
5) RIH w/ workstring to 5800' Pump 50 sx stub plug. Wait 4 hrs, tag plug.
6) Pump 40 sx courtesy plug @2500'. POOH w/workstring to 441'. Pump approx 265 sx shoe plug. Cement to surface.
6) RIH. Tag shoe plug.
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.