

WORKOVER PROCEDURE

WELL NAME: VELVET 21-17 DATE: 8/14/2012

LOCATION: \_\_\_\_\_

Qtr/Qtr: NENW Section: 17 Township: 10N Range: 61W
COUNTY: WELD STATE: CO API #: 05-123-10381

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 200' KB Elevation: 5116
Surface Cmt: 150 sx GL Elevation: 5108
Long St Csg: 4 1/2" 11.60# @ 7634' TD: 7650
Long St Cmt: 150 sx PBTD: 7624
Long St Date: 8/18/1981

Plug Back (Sand or CIBP):
Perforation Interval (1): J Sand Perfs 7518' - 7524', 7527' - 7538'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" tbg @ 5030' Rods: 3/4" Rods, 197 jts set @ 4925'
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ rods and lay down.
3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
4) RU WL. RIH w/CIBP. Set CIBP @ 7418', dump bail 2 sx of cement on top.
5) Unland casing. Cut casing off +/- 7000'. POOH with casing laying down on trailer.
6) RIH w/ workstring to 7000' Pump 100 sx stub plug. Wait 4 hrs, tag plug.
7) Pump 50 sx courtesy plug @2500'. POOH w/workstring to 300'. Pump approx 150 sx shoe plug. Cement to surface.
8) RIH. Tag shoe plug. Add additional cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.