

WORKOVER PROCEDURE

WELL NAME: PREMIER 12-03 DATE: 10/4/2012

LOCATION: Qtr/Qtr: SWNW Section: 3 Township: 2N Range: 62W
COUNTY: WELD STATE: CO API #: 05-123-07049

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 128' KB Elevation: 4733
Surface Cmt: 90 sx GL Elevation: 4724
Long St Csg: 4 1/2" 10.50# @6983' TD: 7000
Long St Cmt: 200 sx PBTD: 6904
Long St Date: 6/4/1973

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 6849' - 6901'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# Set @ 6827' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: Well validation shows a CBL. Not in well file or on COGCC website. Will update if we find a CBL

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6749', dump bail 2 sx of cement on top.
- 4) Run CBL to determine top of cement
- 5) Unland casing. Cut casing off +/- 100' above TOC. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to depth where csg was pulled. Pump (100) sx stub plug. Wait 4 hrs, tag plug.
- 7) Pump (50) sx plug @2500'. POOH w/workstring to 300'. Pump approx 150 sx shoe plug. Cement to surface.
- 8) Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.