

WORKOVER PROCEDURE

WELL NAME: LILLI UNIT 02-07 DATE: 10/5/2012
 LOCATION: Qtr/Qtr: NWNE Section: 7 Township: 8N Range: 58W
 COUNTY: WELD STATE: CO API #: 05-123-13901

ENGINEER: KIMBERLY HILL 7 Day Notice Sent: _____
 (Please notify Engineer of any major Do not start operations until: _____
 changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 228' KB Elevation: 4807
 Surface Cmt: 155 sx Class H GL Elevation: 4798
 Long St Csg: 4 1/2" 10.50# @ 6608' TD: 6610
 Long St Cmt: 200 sx 50/50 POZ PBTD: 6605.5
 Long St Date: 4/5/1988

Plug Back (Sand or CIBP): _____
 Perforation Interval (1): D Sand Perfs 6486' - 6496'
 Perforation Interval (2): _____
 Perforation Interval (3): _____

Tubing: 2 3/8" 4.70# J-55 tbg @ 6182' Rods: Rods set @ 6116' (3/4" Rods - 244 jts)
 Pump: _____
 Misc.: Cement Squeeze -- (5,350'-3,382')

PRODUCTION STATUS: _____
 COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Release tubing anchor. POOH w/ rods. Lay down.
- 3) POOH w/ 2 3/8" tbg. Lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6350', dump bail 2 sx of cement on top.
 (THIS STEP WAS COMPLETED ON 9/6/2012)
- 5) Perforate @ ~2500'
- 6) Set cement retainer above perforations, sting in w/ workstring and pump 90 sx through retainer
- 7) Un-sting from cement retainer and pump 10 sx cement above retainer
- 8) Unland csg, calculate stretch to determine if we can pull
- 9) Cut and pull csg between 1000' - 1500'
- 10) RIH w/ workstring, pump 50 sx stub plug where csg was pulled
- 11) POOH w/ workstring to 328', pump approx 215 sx show plug. Cement to surface.
- 12) RIH. Tag shoe plug. Add cement if needed.
- 13) Cut surface casing off 6'-8' below ground.
- 14) Clean up location. Reclaim location. RDMO.