

WORKOVER PROCEDURE

WELL NAME: SINJIN E 36-16 DATE: 10/11/2012
LOCATION: _____
Qtr/Qtr: SESE Section: 36 Township: 6N Range: 65W
COUNTY: WELD STATE: CO API #: 05-123-16469

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 345' KB Elevation: 4650
Surface Cmt: 300 sx GL Elevation: 4640
Long St Csg: 2 7/8" 6.5# @ 6989' TD: 7007
Long St Cmt: 300 sx PBSD: 6965
Long St Date: 12/17/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): CODELL PERFORATIONS 6867' - 6877'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/CIBP. Set CIBP @ 6767', dump bail 2 sx of cement on top.
- 3) Unland casing. Cut casing off +/- 5700'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to 5700' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 5) Pump (50) sx plug @2500'. POOH w/workstring to 445'. Pump approx 200 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.