

WORKOVER PROCEDURE

WELL NAME: EISENSTAT 22-11 DATE: 10/11/2012

LOCATION: _____

Qtr/Qtr: NENE Section: 22 Township: 6N Range: 64W

COUNTY: WELD STATE: CO API #: 05-123-20100

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 368' KB Elevation: 4736

Surface Cmt: 119 sx GL Elevation: 4724

Long St Csg: 4 1/2" 44.6# @ 7051' TD: 7068

Long St Cmt: 425 sx PBTD: 7012

Long St Date: _____

Plug Back (Sand or CIBP): _____

Perforation Interval (1): CODELL PERFS 6915' - 6928'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# @ 6894' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6815', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 3700'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 3700' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 468'. Pump approx 200 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.