

WORKOVER PROCEDURE

WELL NAME: GILL LAND 22-01 DATE: 10/11/2012

LOCATION: _____

Qtr/Qtr: SENE Section: 22 Township: 6N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-10789

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 231' KB Elevation: 4735
Surface Cmt: 200 sx GL Elevation: 4725
Long St Csg: 4 1/2" 11.6# @ 7083' TD: 7508
Long St Cmt: 225 sx PBTD: 7040
Long St Date: 9/10/1982

Plug Back (Sand or CIBP): _____
Perforation Interval (1): NIOBRARA PERFS 6658' - 6685', 6728' - 6758'
Perforation Interval (2): CODELL PERFS 6913' - 6925'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# @ 6902' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6558', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 6300'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 6300' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 350'. Pump approx 150 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.