

WORKOVER PROCEDURE

WELL NAME: CPC OSTER 19-01 DATE: 11/15/2012

LOCATION: Qtr/Qtr: NENE Section: 19 Township: 4N Range: 64W

COUNTY: WELD STATE: CO API #: 05-123-12442

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 312' KB Elevation: 4807
Surface Cmt: 210 sx GL Elevation: 4796
Long St Csg: 4 1/2" 11.6# @ 7159' TD: 7167
Long St Cmt: 135 sx PBTD: 7100
Long St Date: 5/31/1985

Plug Back (Sand or CIBP):
Perforation Interval (1): NIOBRARA PERFS 6769' - 6866', 6917' - 6938'
Perforation Interval (2): CODELL PERFS 7029' - 7059'
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 @ 7039' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS: NO CBL in Well File, CBL on COGCC Website

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tubing. And lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6669", dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 6400'. POOH with casing laying down on trailer.
5) RIH w/ workstring to Pump (100) sx stub plug where cement was cut. If maintain circulation, do not need to tag plug.
6) Pump (50) sx plug @2500'. POOH w/workstring to 412'. Pump approx 200 sx shoe plug. Cement to surface.
7) RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.