

## WORKOVER PROCEDURE

WELL NAME: CHAMPLIN 32-04 02 DATE: 11/27/2012

LOCATION: Qtr/Qtr: SWNE Section: 4 Township: 1N Range: 68W  
COUNTY: WELD STATE: CO API #: 05-123-08646

ENGINEER: LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 618' KB Elevation: 5048  
Surface Cmt: 400 sx GL Elevation: 5038  
Long St Csg: 5 1/2" 15.5# @ 5220' TD: 5223  
Long St Cmt: 300 sx PBTD: 5172  
Long St Date: 5/13/1976

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Sussex Perforations 4614' - 4672'  
Perforation Interval (2): Shannon Perforations 5084' - 5106'  
Perforation Interval (3): \_\_\_\_\_

Tubing: 2 3/8" 4.7# @ 5160' Rods: 1 1/4" Polished Rod, 5/8" Rods  
Pump: 1 1/2" BHD Pump (3325' 133 jts), 3/4" Rods (1770'  
Misc.: Tubing anchor @ 4464' 71 jts)

PRODUCTION STATUS: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods and lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tubing. And lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 4514', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to 2500' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 718'. Pump approx 300 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.