

WORKOVER PROCEDURE

WELL NAME: MOSER 28-02 DATE: 11/27/2012

LOCATION: _____

Qtr/Qtr: NWNE Section: 28 Township: 3N Range: 65W
COUNTY: WELD STATE: CO API #: 05-123-16054

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 707' KB Elevation: 4838
Surface Cmt: 320 sx GL Elevation: 4826
Long St Csg: 2 7/8" 6.5# @ 7279' TD: 7279
Long St Cmt: 250 sx PBTD: 7086
Long St Date: 10/6/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6962' - 7018'
Perforation Interval (2): Codell Perforations 7140' - 7150'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: Fish in hole @ 7086', could not remove 12/2003

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH w/CIBP. Set CIBP @ 6862', dump bail 2 sx of cement on top.
- 3) Unland casing. Cut casing off +/- 3750'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to 3750' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 5) Pump (50) sx plug @2500'. POOH w/workstring to 800'. Pump approx 300 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.