

WORKOVER PROCEDURE

WELL NAME: KEISER 01 DATE: 2/8/2013

LOCATION: _____

Qtr/Qtr: NESW Section: 33 Township: 5N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-12144

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36# @ 518' KB Elevation: 4676

Surface Cmt: 350sx GL Elevation: 4663

Long St Csg: 4 1/2" 10.5# @ 7154' TD: 7186

Long St Cmt: 550 sx PBTD: 6475

Long St Date: 12/22/1984

Plug Back (Sand or CIBP): Possible Collapsed Casing @ 6487'

Perforation Interval (1): Niobrara Perforations 6744' - 6950'

Perforation Interval (2): Codell Perforations 7047' - 7063'

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# @ 6476' Rods: _____

Pump: _____

Misc.: CBL on COGCC Website, not in wellfile (TOC @ 5934')

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring, pump 20 sx plug from 6487' - 6287'. If maintain circulation do not need to tag plug.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 620'. Pump approx 300 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.