

1. Provide notice to COGCC prior to MIRU per Form 6 COA.
2. Call foreman or Lead Operator before rig up to isolate and remove automation and production equipment. Install fence if needed.
3. Notify CDC when rig moves on location to generate work order for flowline removal and one call for line locates.
4. MIRU slickline services. Pull bumper spring and tag for fill. POOH
5. Run gyro from 8220' to surface making stops every 100'. RDMO slickline services.
6. Place cement services on will call when rig moves on location, providing expected volumes of cement needed. (~75 sx plug #1; ~560 sx plug #2; ~150 sx plug #3)
7. MIRU WO rig. Kill well, as necessary, with water containing biocide. ND wellhead. NU BOP's. Unseat landing joint and lay down.
8. TOOH and stand back 2-3/8" tbg.
9. PU and TIH with casing scraper & bit for 4.5 casing. Scrape casing to ~8180'. Circulate hole clean. TOOH and lay down scraper and bit and stand back tubing.
10. MIRU wireline services. PU 4-1/2" CIBP and RIH to 8170', set CIBP. POOH.
11. PU cement bailer. RIH to CIBP and dump bail 2 sx of cement on top of CIBP.
12. Pressure test plug to 1500 psi for 15 min. RDMO wireline services.
13. TIH w/ 2-3/8" tbg hydrotesting to 3000 psi to CIBP @ 8170'.
14. Circulate Hole, filling with at least 9 ppg mud.
15. MIRU cementing services. Mix and Pump 75 sx of Class "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. (yield 1.38 ft<sup>3</sup>/sx, 15.8 ppg, ~18.5 bbl slurry). Pump balanced plug from CIBP (~8170) – 7000'.
16. PUH 64 jts (~2016') to 6154' laying down tubing and circulate hole with at least 9 ppg mud w/ biocide to remove any cement. RDMO cementing services. TOOH and stand back 4850' of tbg, lay down remaining tubing.
17. MIRU wireline services. PU perf gun loaded with 1' of 3 spf, 0.6" EHD, 7" penetration, 120 phasing. RIH to 6038' and shoot perfs. POOH
18. PU 4-1/2" CICR and RIH to 4850'. Set CICR. POOH. RDMO wireline services
19. TIH w/ 2-3/8" tbg to 4850' and sting into CICR. Establish circulation through CICR.
20. MIRU cementing services. Preflush with 5 bbl H<sub>2</sub>O, 20 bbl of sodium metasilicate, 5 bbl H<sub>2</sub>O.
21. Mix and Pump 560 sx of Class "G" cement with ¼ #/sx cello-flake, 0.4% CD-32 and 0.4% ASA-301 through CICR (yield 1.15 ft<sup>3</sup>/sx, 15.8 ppg, ~114.5 bbl slurry). Pump cement through CICR. Underdisplace cement by 1 bbl; leaving 1 bbl of cement on top of CICR.
22. PUH 90 jts (~2835') to 2015' laying down tubing and circulate hole with at least 9 ppg mud to remove any cement. RDMO cementing services. TOOH and stand back 1900' of tbg, lay down remaining tubing.
23. MIRU wireline services. Shoot off casing @ 1800'. RDMO wireline services.
24. NDBOP NDTH. Unland casing from slips.
25. NU BOP on casing head. Install 4-1/2" pipe rams.

26. PU casing and conventionally circulate 250 bbl of mud. If circulation cannot be established contact engineer and COGCC for change in procedure.
27. TOOH with 4-1/2" casing and lay down.
28. PU 2-3/8" tbg and TIH into casing stub to 1900'.
29. MIRU cementing services. Mix and pump 150 sx of Type III cement from 1900' to 1300' (yield 1.53 ft<sup>3</sup>/sx, 14 ppg, ~40.5 bbl slurry). Displace cement. RDMO cementing services.
30. TOOH to 100' (standing back 1300' of tubing and laying down remaining tubing). Circulate 10 bbl of mud to remove any cement. WOC 4 hrs or overnight.
31. TIH and tag cement plug, NOTE: DEPTH OF PLUG IN OPENWELLS. If plug top is above 1576' TOOH and lay down tubing.
32. MIRU wireline services. PU 8-5/8" CIBP and RIH to 100'. Set CIBP and POOH. Pressure test CIBP to 1000 psi for 15 minutes. RDMO wireline services.
33. RDMO WO Rig.
34. Wellsite supervisor turn all paper copies of cementing reports/invoices and logs in to Sabrina Frantz. NOTE: During the job, wellsite supervisor should instruct the logging and cementing contractors to e-mail all logs, job reports/invoices to Sabrina Frantz.
35. Have excavation contractor notify One-Call to clear for digging around wellhead and flowline removal.
36. Check top of cement inside 8-5/8" surface casing., place redi-mix cementer on will call. (6.5 bbl)
37. Excavate hole around surface casing of sufficient size and depth to allow welder to cut off 8-5/8" surface casing and at least 5' below ground level.
38. Have welder cut off 8-5/8" surface casing at least 5' below ground level.
39. MIRU ready cement mixer. Use 4,500 psi compressive strength redi-mix cement (sand and cement only, no gravel) to finish filling surface casing and production casing to top of cut off.
40. Have welder spot weld steel marker plate on top of surface casing. (Note: marker shall be labeled with well name and number, legal location (¼ ¼ description) and API number.
41. Properly abandon flowlines as per Rule 1103.
42. Have excavation contractor back fill hole with native material. Clean up location and have leveled to plant any vegetation required.
43. Submit Form 6 to COGCC. Provide "As Plugged" wellbore diagram identifying the specific plugging completed.

HSR-Van Schaack 6-11 a 1995 J-Sand completion. Negative operating income with a hole in tubing make this well a good P&A candidate.