

## WORKOVER PROCEDURE

WELL NAME: DINNER 14-01 DATE: 1/29/2013

LOCATION: Qtr/Qtr: SWSW Section: 14 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-10788

ENGINEER: LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 298' KB Elevation: 4725  
Surface Cmt: 110 sx GL Elevation: 4715  
Long St Csg: 4 1/2" 11.6# @ 7612' TD: 7617  
Long St Cmt: 315 sx PBTD: 7599  
Long St Date: 9/18/1982'

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6754' - 6894'  
Perforation Interval (2): Codell Perforations 7041' - 7054'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 7014' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

PRODUCTION STATUS: \_\_\_\_\_  
COMMENTS: \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6654', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 400'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.