

WORKOVER PROCEDURE

WELL NAME: UPV 05-05J3 **DATE:** 11/30/2012

LOCATION: _____

Qtr/Qtr: SWNW Section: 5 Township: 3N Range: 63W

COUNTY: WELD **STATE:** CO **API #:** 05-123-18381

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# @ 597' KB Elevation: 4847

Surface Cmt: 310 sx GL Elevation: 4833

Long St Csg: 4 1/2" 11.6# @ 7429' TD: 7429

Long St Cmt: 100 sx PBTD: 7390

Long St Date: 8/6/1993

Plug Back (Sand or CIBP): _____

Perforation Interval (1): J Sand Perforations 7298' - 7318'

Perforation Interval (2): _____

Perforation Interval (3): _____

Tubing: 2 3/8" 4.7# J-55 @ 7259' Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7198', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 5000' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 697'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.