

WORKOVER PROCEDURE

WELL NAME: GARCIA MD01-12 **DATE:** 11/29/2012

LOCATION:

COUNTY: Qtr/Qtr: NWSW Section: 1 Township: 1S Range: 69W
BOULDER STATE: CO API #: 05-013-06448

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 824' KB Elevation: 5164.5
Surface Cmt: 330 sx GL Elevation: 5154
Long St Csg: 3 1/2" 7.7# @ 8235' TD: 8253
Long St Cmt: 260 sx PBTD: 8220
Long St Date: 10/21/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7671' - 7852'
Perforation Interval (2): Codell Perforations 8088' - 8101'
Perforation Interval (3): _____
Tubing: 1.9" 2.75# J-55 tbg Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tubing. And lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7571', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 6500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to 6500' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
- 6) Pump (50) sx plug @2500'. POOH w/workstring to 924'. Pump approx 350 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.