

WORKOVER PROCEDURE

WELL NAME: DOM RED X20-03 **DATE:** 4/24/2013
LOCATION:
Qtr/Qtr: NENW Section: 20 Township: 2N Range: 65W
COUNTY: WELD **STATE:** CO **API #:** 05-123-17165

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 854' KB Elevation: 4935
Surface Cmt: 590 sx GL Elevation: 4922
Long St Csg: 2 7/8" 6.4# @ 7461' TD: 7467
Long St Cmt: 217 sx PBTD: 7297
Long St Date: 7/28/1993

Plug Back (Sand or CIBP): **Sand Plug 7200' - 7395', RBP @ 6927'**
Perforation Interval (1): Niobrara Perforations 7054' - 7162'
Perforation Interval (2): Codell Perforations 7288' - 7305'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH and dump bail 2 sx of cement on top of RBP @6927'.
- 3) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 5) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 950'. Pump approx 350 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.