

WORKOVER PROCEDURE

WELL NAME: CASE 01 **DATE:** 4/24/2013
LOCATION:
Qtr/Qtr: NENE Section: 17 Township: 1S Range: 66W
COUNTY: ADAMS **STATE:** CO **API #:** 05-001-06790
ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 113' KB Elevation: 5043
Surface Cmt: 110 sx GL Elevation: 5033
Long St Csg: 4 1/2" 11.60# @ 8237' TD: 8237
Long St Cmt: 250 sx PBTD: _____
Long St Date: 2/12/1974

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 8104' - 8134'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/2" @ 8087' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 8004', dump bail 2 sx of cement on top.
- 4) Run CBL to determine TOC.
- 5) RIH w/ workstring to pump 20 sx plug @ 3000'. (Adjust depth if no cement coverage from CBL).
- 6) Unland casing. Cut casing off +/- 1000'. POOH with casing laying down on trailer. (Depth depending on CBL).
- 7) RIH w/ workstring to pump approx 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 8) POOH w/workstring to 300'. Pump approx 125 sx shoe plug. Cement to surface.
- 9) RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.