

## WORKOVER PROCEDURE

**WELL NAME:** TASHIRO-UPRR 01 **DATE:** 4/25/2013

**LOCATION:** Qtr/Qtr: SWSW Section: 17 Township: 1S Range: 66W

**COUNTY:** ADAMS **STATE:** CO **API #:** 05-001-06841

**ENGINEER:** LEAH PERKINS  
(Please notify Engineer of any major changes prior to work)

7 Day Notice Sent: \_\_\_\_\_  
Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:**

Surface Csg:	8 5/8" 24# @ 158'	KB Elevation:	5039
Surface Cmt:	150 sx	GL Elevation:	5029
Long St Csg:	4 1/2" 11.6# @ 8210'	TD:	8225
Long St Cmt:	250 sx	PBTD:	
Long St Date:	5/26/1974		

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): J Sand Perforations 8116' - 8135'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/2" tbg @ 8100' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 8016', dump bail 2 sx of cement on top.
- 4) Run CBL to determine TOC.
- 5) Perforate @ 2500' and set CICR. Pump 90 sx through CICR and 10 sx on top.
- 6) POOH w/workstring to 1200'. Pump approx 120 sx shoe plug. Cement to surface. (Confirm cement in annulus on CBL).
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.