

## WORKOVER PROCEDURE

**WELL NAME:** LARSON A25-12 **DATE:** 5/6/2013

**LOCATION:** Qtr/Qtr: NWSW Section: 25 Township: 6N Range: 64W

**COUNTY:** WELD STATE: CO API #: 05-123-14704

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 271' KB Elevation: 4628  
Surface Cmt: 250 sx GL Elevation: 4618  
Long St Csg: 2 7/8" 6.5# @ 6962' TD: 6965  
Long St Cmt: 235 sx PBTD: 6913  
Long St Date: 9/4/1990

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6793' - 6805'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/2" 2.76# J-55 @ 6774' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6693', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump a 10 sx plug @ 3500'. If maintain circulation, do not need to tag plug.
- 5) POOH w/workstring to 440'. Pump approx 20 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.