

WORKOVER PROCEDURE

WELL NAME: SPIKE STATE C24-13 **DATE:** 3/27/2013

LOCATION: Qtr/Qtr: SWSW Section: 24 Township: 4N Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-15813

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg:	8 5/8" 24# @ 349'	KB Elevation:	4713
	Surface Cmt:	220 sx	GL Elevation:	4700
	Long St Csg:	2 7/8" 6.5# @ 6936'	TD:	6962
	Long St Cmt:	260 sx	PBTD:	6896
	Long St Date:	8/6/1992		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): _____ Codell Perforations 6796' - 6806'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" 2.33# J-55 @ 6758' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6696', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 1500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 450'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.