

WORKOVER PROCEDURE

WELL NAME: LARSON A25-7 **DATE:** 6/13/2013

LOCATION:
Qtr/Qtr: SWNE Section: 25 Township: 6N Range:
COUNTY: WELD **STATE:** CO **API #:**

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 273' KB Elevation:
Surface Cmt: 250 sx GL Elevation:
Long St Csg: 2 7/8" 6.50# @ 6938' TD:
Long St Cmt: 320 sx PBTD:
Long St Date: 10/9/1990

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 6783' - 6795'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1.9" 2.76# J-55 tbg @ 6746' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6683', dump bail 2 sx of cement on top.
(If can not set CIBP in slimhole csg, RIH w/ workstring and pump 10 sx plug.)
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plu
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 375'. Pump approx 150 sx shoe plug. Cement to sur
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.

64W
05-123-14721

4646
4636
6940
6875

ig.

face.