

WORKOVER PROCEDURE

WELL NAME: LOUSTALET B15-16 DATE: 6/17/2013
LOCATION:
Qtr/Qtr: SESE Section: 15 Township: 5N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-15015

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 343' KB Elevation: 4581
Surface Cmt: 220 sx GL Elevation: 4571
Long St Csg: 2 7/8" 6.50# @ 6913' TD: 6932
Long St Cmt: 325 sx PBTD: 6699
Long St Date: 7/21/1991

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 6689' - 6707'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1.9" 2.75# J-55 @6670' Rods:
Pump:
Misc.: Csg Patch @ 5196'

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 1.9" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6589', dump bail 2 sx of cement on top. (If cannot set CIBP, pump balanced plug to at least 6590')
4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 440'. Pump approx 175 sx shoe plug. Cement to surface.
7) RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.