

WORKOVER PROCEDURE

WELL NAME: KEHN USX AD19-11 **DATE:** 4/2/2013

LOCATION: Qtr/Qtr: NESW Section: 19 Township: 7N Range: 62W

COUNTY: WELD STATE: CO API #: 05-123-26045

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg: <u>8 5/8" 24# @ 477'</u>	KB Elevation: <u>4763</u>
	Surface Cmt: <u>232 sx</u>	GL Elevation: <u>4753</u>
	Long St Csg: <u>4 1/2" 11.6# @ 6883'</u>	TD: <u>6904</u>
	Long St Cmt: <u>720 sx</u>	PBTD: <u>6825</u>
	Long St Date: <u>5/17/2008</u>	

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6507' - 6626'
Perforation Interval (2): Codell Perforations 6730' - 6740'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 6812' Rods: 7/8" Rods - 89 jts, 3/4" Rods-180 j
Pump: 2" Insert Pump
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: CBL not in well file, on COGCC Website

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods and lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6407', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 1500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 577'. Pump approx 250 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.