

WORKOVER PROCEDURE

WELL NAME: EVANS INDUSTRIAL PARK 02 **DATE:** 6/27/2013

LOCATION: Qtr/Qtr: NWSE Section: 30 Township: 5N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-16656

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 376' KB Elevation: 4666
Surface Cmt: 385 sx GL Elevation: 4655
Long St Csg: 4 1/2" 11.6# @ 7204' TD: 7227
Long St Cmt: 335 sx PBTD: 7117
Long St Date: 1/27/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7078' - 7094'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 7061' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: CBL on COGCC Website

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6978', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 3500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 475'. Pump approx 180 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.