

**WORKOVER PROCEDURE**

**WELL NAME:** D CASTOR 1 **DATE:** 6/27/2013

**LOCATION:** \_\_\_\_\_

Qtr/Qtr: NENW Section: 21 Township: 8N Range: 59W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-05528

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 28# @ 127' KB Elevation: 4814  
Surface Cmt: 85 sx GL Elevation: 4809  
Long St Csg: 4 1/2" 11.60# @ 6700' TD: 6700  
Long St Cmt: 150 sx PBTD: 6654  
Long St Date: 8/13/1975

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): D Sand Perforations 6616' - 6622'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# @ 6636' Rods: 3/4" string  
Pump: Rod Pump 2" OD  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ rods and lay down.
- 3) Release tubing anchor. POOH w/ 2 3/8" tbg and lay down.
- 4) RU WL. RIH w/CIBP. Set CIBP @ 6516', dump bail 2 sx of cement on top.
- 5) Run CBL to determine TOC.
- 6) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 8) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 300'. Pump approx 125 sx shoe plug. Cement to surface.
- 9) RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.