

WORKOVER PROCEDURE

WELL NAME: BAKER B02-04 **DATE:** 7/10/2013
LOCATION:
Qtr/Qtr: NWNW Section: 2 Township: 5N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-13800

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 262' KB Elevation: 4648
Surface Cmt: 175 sx GL Elevation: 4637
Long St Csg: 4 1/2" 15.10# @ 6947' TD: 6955
Long St Cmt: 220 sx PBTD: 6919
Long St Date: 1/30/1988

Plug Back (Sand or CIBP): **RBP @ 6453', Sand Plug 6448'-6453'**
Perforation Interval (1): Niobrara Perfs 6528' - 6720'
Perforation Interval (2): Codell Perfs 6802' - 6810'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RIH w/ workstring. Circulate sand off of RBP. Pump 10 sx plug on top of RBP from 6453' - 6353'.
If maintain circulation, do not need to tag plug.
- 3) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 5) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 362'. Pump approx 150 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.