

**WORKOVER PROCEDURE**

**WELL NAME:** MOSER H 34-04 **DATE:** 7/10/2013

**LOCATION:** \_\_\_\_\_

Qtr/Qtr: NWNW Section: 34 Township: 3N Range: 65W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-15450

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 535' KB Elevation: 4840  
Surface Cmt: 450 sx GL Elevation: 4830  
Long St Csg: 2 7/8" 6.50# @ 7289' TD: 7310  
Long St Cmt: 300 sx PBTD: 7282  
Long St Date: 12/4/1991

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7145' - 7159'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/4" 2.3# J-55 @ 7125' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7045', dump bail 2 sx of cement on top. (If can not set CIBP in 2 7/8" csg, pump balance plug to at from 7210' to at least 7000'. Wait 4 hours, tag plug.)
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 635'. Pump approx 250 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.