

WORKOVER PROCEDURE

WELL NAME: BLAKE B29-09 **DATE:** 7/1/2013
LOCATION:
Qtr/Qtr: NESE Section: 29 Township: 5N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-15412

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 308' KB Elevation: 4690
Surface Cmt: 200 sx GL Elevation: 4680
Long St Csg: 2 7/8" 6.50# @ 7059' TD: 7083
Long St Cmt: 270 sx PBTD: 6497
Long St Date: 12/22/1991

Plug Back (Sand or CIBP): **RBP @ 6422', Sand Plug 6497' - 7030'**
Perforation Interval (1): Niobrara Perfs 6608' - 6730'
Perforation Interval (2): Codell Perfs 6900' - 6913'
Perforation Interval (3): _____
Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. RIH and dump bail 2 sx of cement on top of RBP @ 6422'.
- 3) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 4) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 5) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 408'. Pump approx 175 sx shoe plug. Cement to surface.
- 6) RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.