

## WORKOVER PROCEDURE

**WELL NAME:** CAVALIER 32-35 **DATE:** 7/23/2013  
**LOCATION:**  
Qtr/Qtr: SWNE Section: 35 Township: 1S Range: 64W  
**COUNTY:** ADAMS **STATE:** CO **API #:** 05-001-09544

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 1461' KB Elevation: 5222  
Surface Cmt: 1025 sx GL Elevation: 5210  
Long St Csg: 4 1/2" 11.60# @ 7866' TD: 7898  
Long St Cmt: 200 sx PBTD: 7847  
Long St Date: \_\_\_\_\_

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): J Sand Perforations 7748' - 7754'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.70# @ 7738' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7648', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 1700'. Pump approx 200 sx shoe plug. Wait 4 hours, tag plug.
- 7) Pump 50 sx plug at surface.
- 8) RIH. Tag plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.