

WORKOVER PROCEDURE

WELL NAME: Trebor B11-19 DATE: 7/24/2013

LOCATION: Qtr/Qtr: NENW Section: 11 Township: 5N Range: 64W
COUNTY: WELD STATE: CO API #: 05-123-26659

ENGINEER: Brittany Smyth 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: Annular Fill

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 470' KB Elevation: 4609'
Surface Cmt: 470' GL Elevation: 4399'
Long St Csg: 4 1/2" 11.6# M-80 @ 6903' TD: 6910'
Long St Cmt: 1954' - TOC PBTD: 6887'
Long St Date: 1/3/2008

Plug Back (Sand or CIBP): TAG
Perforation Interval (1): NIO 6459'- 6576'
Perforation Interval (2): CODELL 6739'- 6753'
Perforation Interval (3):

Tubing: 2 3/8" 4.7# J55 @ 6711' Rods:
Pump:
Misc.:

PRODUCTION STATUS: Producing - 10.3 BOEPD
COMMENTS: Base Fox Hills @ 254'

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) Control well with kill fluid
3) POOH 2 3/8" tubing
4) RIH w/ Bit & Scraper. Tag fill if any. Clean out to PBTD (tally in). TOOH
5) RIH w/RBP. Set RBP @ +/-6409', spot 2 sx of sand on top of RBP. Test RBP 2,000psi. TOOH
6) Bleed off bradenhead, unland casing
7) Trip in 1 1/4" tubing down annular w/ mule shoe to 1200', condition hole.
8) RU cement crew, pump 144 sxs 15.8ppg "G" neat cement to cover the interval 700'-1100'.
9) POOH with 1 1/4" tubing, land casing.
10) SI well overnight, run CBL recording new cement depths
11) Clean out hole