

WORKOVER PROCEDURE

WELL NAME: MEYER B 02-01 **DATE:** 7/30/2013

LOCATION: Qtr/Qtr: NENE Section: 2 Township: 5N Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-13449

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg:	8 5/8" 24# @ 313'	KB Elevation:	4620
	Surface Cmt:	220 sx	GL Elevation:	4610
	Long St Csg:	2 7/8" 6.50# @ 6897'	TD:	6926
	Long St Cmt:	245 sx	PBTD:	6842
	Long St Date:	10/21/1993		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): _____ Niobrara Perfs 6473' - 6662'
Perforation Interval (2): _____ Codell Perfs 6773' - 6784'
Perforation Interval (3): _____
Tubing: 1 1/4" J55 NUE Tbg @ 6757' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6373', dump bail 2 sx of cement on top.
- 4) Run CBL to confirm cement coverage from csg repair. (4300' to surface). *If not cemented to surface, consult engineer for procedure modification (Either perforate or annular fill to surface).
- 5) Pump 5 sx balanced plug @ 4000'. (If cement coverage is confirmed behind csg). If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 500'. Pump approx 25 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.