

**WORKOVER PROCEDURE**

**WELL NAME:** LUCCI BCB 01-03 **DATE:** 7/23/2013

**LOCATION:** Qtr/Qtr: NENW Section: 1 Township: 5N Range: 64W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-13172

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 307' KB Elevation: 4629  
Surface Cmt: 250 sx GL Elevation: 4617  
Long St Csg: 4 1/2" 15.10# @ 6878' TD: 6908  
Long St Cmt: 230 sx PBSD: 6835  
Long St Date: 10/2/1986

Plug Back (Sand or CIBP): CIBP @ 6382' w/ cmt on top  
Perforation Interval (1): Niobrara Perforations 6490' - 6677'  
Perforation Interval (2): Codell Perforations 6768' - 6780'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
  - 2) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
  - 3) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
  - 4) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 410'. Pump approx 175 sx shoe plug. Cement to surface.
  - 5) RIH. Tag shoe plug. Add cement if needed.
  - 6) Cut surface casing off 6'-8' below ground.
  - 7) Clean up location. Reclaim location. RDMO.