

**WORKOVER PROCEDURE**

**WELL NAME:** CORLISS 21-33 **DATE:** 8/7/2013

**LOCATION:** Qtr/Qtr: NENW Section: 33 Township: 5N Range: 63W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-21003

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# J-55 @ 423' KB Elevation: 4576  
Surface Cmt: 345 sx GL Elevation: 4564  
Long St Csg: 4 1/2" 11.60# N-80 @ 7347' TD: 7348  
Long St Cmt: 275 sx PBTD: 7330  
Long St Date: 11/5/2003

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Dakota Perforations 7240' - 7274'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.70# J-55 tbg @ 7274' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: 3-3/8" Tubing conveyed perforating gun and assembly left in hole

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
  - 2) POOH w/ 2 3/8" tbg and lay down.
  - 3) RU WL. RIH w/CIBP. Set CIBP @ 7140', dump bail 2 sx of cement on top.
  - 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
  - 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
  - 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 530'. Pump approx 200 sx shoe plug. Cement to surface.
  - 7) RIH. Tag shoe plug. Add cement if needed.
  - 8) Cut surface casing off 6'-8' below ground.
  - 9) Clean up location. Reclaim location. RDMO.