

REENTRY PROCEDURE

WELL NAME: STATE 5-36 DATE: 7/23/2013  
 LOCATION: Qtr/Qtr: SWSW Section: 36 Township: 9N Range: 59W  
 COUNTY: WELD STATE: CO API #: 05-123-14657

ENGINEER: Amanda Beck 7 Day Notice Sent: \_\_\_\_\_  
 (Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
 Notice Expires: \_\_\_\_\_

OBJECTIVE: Reenter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 256' KB Elevation: 4842'  
 Surface Cmt: 130 SX GL Elevation: 4832'  
 Long St Csg: 7 7/8" open hole to 6080'; 4 1/2" 10.5# TO TD TD: 6721'  
 Long St Cmt: 200 SX - TOC 6384' PBTD: \_\_\_\_\_  
 Long St Date: 8/13/1990

Plug Info (1) CIBP + 2 sx @ 6300'  
 Plug Info (2) 35 sx 1/2 in 1/2 out of surface casing  
 Plug Info (3) 10 sx @ surface  
 Plug Info (4)

Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
 Pump: \_\_\_\_\_  
 Misc.: **Base Fox Hills 617', Deepest water well 695'**

WELL STATUS: Well Abandoned 3/21/91

COMMENTS: Cut pipe 4' below ground, welded on steel cap

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging.
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 3000'
- 15) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 3000'.
- 17) RU cement crew and pump a balanced plug of 100sk 15.8 ppg Class G "neat" cement
- 18) POOH to 845' (150' below deepest water well@ 695')
- 19) RU cement crew and pump 316 sxs of 15.8ppg Class G "neat" cement bring cement to surface
- 20) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 21) Let cement set over night, verify cement has not settled and is still at surface. RDMO