

WORKOVER PROCEDURE

WELL NAME: TANNER K 33-12 **DATE:** 8/15/2013
LOCATION:
Qtr/Qtr: NWSW Section: 33 Township: 4N Range: 66W
COUNTY: WELD **STATE:** CO **API #:** 05-123-15128

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 439' KB Elevation: 4779
Surface Cmt: 220 sx GL Elevation: 4769
Long St Csg: 2 7/8" 6.50# @ 7446' TD: 7482
Long St Cmt: 525 sx PBTD: 7285
Long St Date: 8/30/1991

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perfs 7282' - 7295'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/2" 2.76# @ 7249' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/2" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7182', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 540'. Pump approx 200 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.