

WORKOVER PROCEDURE

WELL NAME: UPV 05-07K3 **DATE:** 9/5/2013
LOCATION:
Qtr/Qtr: SWNE Section: 5 Township: 2N Range: 63W
COUNTY: WELD **STATE:** CO **API #:** 05-123-18352

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# H-40 @ 717' KB Elevation: 4841
Surface Cmt: 375 sx GL Elevation: 4827
Long St Csg: 4 1/2" 11.60# M-75 @ 7390' TD: 7410
Long St Cmt: 130 sx PBTD: 7355
Long St Date: 8/13/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 7296' - 7304'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 7273' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7196', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 817'. Pump approx 300 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.