

WORKOVER PROCEDURE

WELL NAME: CANNON RED W03-04D DATE: 9/4/2013

LOCATION: Qtr/Qtr: NESE Section: 3 Township: 2N Range: 66W

COUNTY: WELD STATE: CO API #: 05-123-16278

ENGINEER: LEAH PERKINS 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# K-55 @ 791' KB Elevation: 5011
Surface Cmt: 380 sx GL Elevation: 5000
Long St Csg: 3 1/2" 12.95# N-80 @ 8222' TD: 8240
Long St Cmt: 500 sx PBTD: 7510
Long St Date: 10/25/1992

Plug Back (Sand or CIBP): RBP @ 6542', SAND PLUG @ 7988'
Perforation Interval (1): Codell Perfs 7453' - 7468'
Perforation Interval (2): Dakota Perfs 8105' - 8144'
Perforation Interval (3):
Tubing: Rods:
Pump:
Misc.: PACKER STUCK @ 7558', TOF @ 7517'

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) RIH w/ workstring. Circulate sand off RBP. Remove RBP.
3) RIH w/ CIBP. Set CIBP @ 7353', dump bail 2 sx of cement on top.
4) Perforate @ 7180' and set CICR. Pump 90 sx through CICR and 10 sx on top.
5) Unland casing. Cut casing off +/- 4500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
7) POOH w/workstring to 890'. Pump approx 320 sx shoe plug. Cement to surface.
8) RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.