

WORKOVER PROCEDURE

WELL NAME: STATE 26-10J2 **DATE:** 9/5/2013

LOCATION: Qtr/Qtr: NWSE Section: 26 Township: 3N Range: 62W

COUNTY: WELD **STATE:** CO **API #:** 05-123-18337

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:	Surface Csg:	7" 17# @ 499'	KB Elevation:	4709
	Surface Cmt:	162 sx	GL Elevation:	4695
	Long St Csg:	4 1/2" 11.70# NS-95 @ 7073'	TD:	7090
	Long St Cmt:	105 sx	PBTD:	7041
	Long St Date:	7/4/1994		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 6766' - 6774'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" tbg @ 6710' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6666', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 600'. Pump approx 150 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.