

## WORKOVER PROCEDURE

**WELL NAME:** LARSON A25-15 **DATE:** 9/11/2013

**LOCATION:** Qtr/Qtr: SWSE Section: 25 Township: 6N Range: 64W

**COUNTY:** WELD STATE: CO API #: 05-123-14749

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 273' KB Elevation: 4646  
Surface Cmt: 250 sx GL Elevation: 4636  
Long St Csg: 2 7/8" 6.50# N-80 @ 6927' TD: 6940  
Long St Cmt: 320 sx PBTD: 6777  
Long St Date: 10/7/1990

Plug Back (Sand or CIBP): RBP @ 6198' w/ sand plug on top  
Perforation Interval (1): Codell Perforations 6785' - 6797'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RIH w/ workstring. Circulate sand off RBP @ 6198'. Retrieve RBP.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6685', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 400'. Pump approx 150 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.