

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
400453786

Date Received:
07/25/2013

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175 Contact Name: Jenifer Hakkarinen
 Name of Operator: PDC ENERGY INC Phone: (303) 8605800
 Address: 1775 SHERMAN STREET - STE 3000 Fax: (303) 8605838
 City: DENVER State: CO Zip: 80203 Email: Jenifer.Hakkarinen@pdce.com

For "Intent" 24 hour notice required, Name: PRECUP, JIM Tel: (303) 726-3822
COGCC contact: Email: james.precup@state.co.us

API Number 05-001-06679-00 Well Number: 1
 Well Name: LETTERLY-SCOTT
 Location: QtrQtr: NENE Section: 24 Township: 1S Range: 67W Meridian: 6
 County: ADAMS Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.953611 Longitude: -104.831944
 GPS Data:
 Date of Measurement: 01/19/2010 PDOP Reading: 1.8 GPS Instrument Operator's Name: Robert Girillego
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	8174	8186			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	23	216	200	216	0	VISU
1ST	7+7/8	5	18	8,268	200	8,268	7,300	CALC
			Stage Tool	1,110	200	1,110	0	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 8150 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 5100 ft. with 200 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 200 sacks half in. half out surface casing from 500 ft. to 0 ft. Plug Tagged:

Set 10 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

Plugging Procedure
J-Sand
Existing Perforations:
J-Sand: 8174'-8186'
PBDT: 8268'
8 5/8" 24# Casing set @ 216' cemented w/ 200 sx
5" 18# Casing set @ 8268' cemented w/ 200 sx
Procedure:
1)MIRU Workover Rig
2)Pull production tubing
3)MIRU wireline
4)RIH w/CIBP set @ 8150'
5)RIH w/dump bailer and dump 2 sx cement on top of CIBP
6)RIH w/guns, perforate at 5100' and 1150'
7)RIH w/cement retainer, set above perms at 5100', circulate 200sx cement to 1150' through casing annulus.
8)TOH and set 200 sack cement plug 500' to surface
9)Set 10 sx @ top of surface
10)Cut casing and weld on cap

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jenifer Hakkarinen

Title: Regulatory Tech Date: 7/25/2013 Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:

Date: 9/14/2013

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 3/13/2014

<u>COA Type</u>	<u>Description</u>
	<p>NOTE: Changes in plugging procedure</p> <ol style="list-style-type: none"> 1) Provide 24 hour notice of MIRU to Jim Precup at 303-726-3822 or e-mail at James.Precup@state.co.us. 2) Run CBL verifying stage cement is from at least 1110' and is 50' into surface casing shoe (160'). If not present, contact COGCC. 3) Place at least 2 sx cement on top of CICR 4) For 500' plug: pump plug and displace, if not circulated to surface - shut-in, WOC 4 hours and tag plug (must be 170' or shallower, place 10 sx inside and outside of casing at surface). Leave at least 100' cement in the casing for each plug. 5) Properly abandon flowlines as per Rule 1103.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400453786	FORM 6 INTENT SUBMITTED
400453835	WELLBORE DIAGRAM
400453836	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	<p>LOCATION: SE1/4 OF NE1/4 OF SEC. 24, T.1s., R.67W. (1585 NSL, 1164 ESL)</p> <p>Ground Elevation: 5010 Number of Acres: 160</p> <p>ELEVATION DEPTH TO ANNUAL ----- NET ----- APPROP STATUS AQUIFER BOT. TOP SAND BOT. TOP A-F ----- UPPER DAWSON ---- - - - - - LOWER DAWSON ---- - - - - - DENVER ---- - - - - - UPPER ARAPAHOE 4875 4902 10.7 135 108 2.92 NNT LOWER ARAPAHOE 4583 4820 110.8 427 190 30.14 NT LARAMIE-FOX HILLS 3911 4143 167.9 1099 867 40.30 NT</p> <p>note: E indicates location is at aquifer boundary and values may be more approximate.</p> <p>Elevation of the bottom and the depth to the bottom of the Upper Arapahoe are approximate and should be checked against DENVER BASIN ATLAS NO. 3</p>	9/14/2013 1:12:43 PM
Permit	Completion or recompletion report doc. # 340686 dated 7/24/1973	7/26/2013 7:07:56 AM

Total: 2 comment(s)