

WORKOVER PROCEDURE

WELL NAME: CALLY WHITE D15-07 **DATE:** 10/2/2013

LOCATION: Qtr/Qtr: SWNE Section: 15 Township: 3N Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-16370

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 522' KB Elevation: 4809
Surface Cmt: 365 sx GL Elevation: 4796
Long St Csg: 4 1/2" 11.60# J-55 @ 7132' TD: 7132
Long St Cmt: 781 sx PBTD: 7055
Long St Date: 11/15/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perfs 4339' - 4512'
Perforation Interval (2): Niobrara Perfs 6678' - 6738'
Perforation Interval (3): Codell Perfs 6944' - 6955'
Tubing: 2 3/8" 4.70# J-55 @ 6927' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6628', dump bail 2 sx of cement on top.
- 4) RIH w/ second CIBP. Set CIBP @ 4289', dump bail 2 sx of cement on top.
- 5) Unland casing. Cut casing off +/- 1500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 622'. Pump approx 250 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.