

WORKOVER PROCEDURE

WELL NAME: _____ **STATE** 03 **DATE:** 10/3/2013

LOCATION: _____

Qtr/Qtr: NWNW Section: 36 Township: 2N Range: 65W
COUNTY: WELD **STATE:** CO **API #:** 05-123-07558

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# K-55 @ 807' KB Elevation: 4941
Surface Cmt: 550 sx GL Elevation: 4928
Long St Csg: 4 1/2" 11.60# K-55 @ 7829' TD: 7829
Long St Cmt: 175 sx PBTD: 7784
Long St Date: 12/13/1972

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 7644' - 7675'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1.9" 2.90# @ 7651' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7594', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 907'. Pump approx 325 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.