

WORKOVER PROCEDURE

WELL NAME: MEISINGER 33-01 **DATE:** 10/8/2013
LOCATION:
Qtr/Qtr: NWSW Section: 33 Township: 5N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-10837

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 341' KB Elevation: 4708
Surface Cmt: 300 sx GL Elevation: 4695
Long St Csg: 4 1/2" 11.60# N-80 @ 6994' TD: 6994
Long St Cmt: 250 sx PBTD: 6870
Long St Date: 10/10/1982

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perfs 6605' - 6777'
Perforation Interval (2): Codell Perfs 6830' - 6840'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 6808' (pckr @ 3488') Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Release Packer. POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6555', dump bail 2 sx of cement on top.
- 4) Run CBL to determine TOC from cement squeeze (Approx 1300').
- 5) Unland casing. Cut casing off +/- 1000'. POOH with casing laying down on trailer. (Adjust depth based on CBL)
- 6) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 440'. Pump approx 175 sx shoe plug. Cement to surface.
- 8) RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.