

WORKOVER PROCEDURE

WELL NAME: SCHOTT B33-13 **DATE:** 10/16/2013
LOCATION:
Qtr/Qtr: SWSW Section: 33 Township: 5N Range: 64W
COUNTY: WELD **STATE:** CO **API #:** 05-123-19328

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 369' KB Elevation: 4704
Surface Cmt: 280 sx GL Elevation: 4694
Long St Csg: 3 1/2" 7.70# M-75 @ 7058' TD: 7073
Long St Cmt: 185 sx PBTD: 6990
Long St Date: 2/8/1997

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6591' - 6690'
Perforation Interval (2): Codell Perforations 6869' - 6881'
Perforation Interval (3): _____
Tubing: 2 1/16" tbg @ 6839' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6540', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 470'. Pump approx 175 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.