

WORKOVER PROCEDURE

WELL NAME: GIES E 05-06 **DATE:** 10/21/2013

LOCATION: Qtr/Qtr: SENW Section: 5 Township: 6N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-12936

ENGINEER: LEAH PERKINS 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 361' KB Elevation: 4825
Surface Cmt: 250 sx GL Elevation: 4814
Long St Csg: 4 1/2" 11.60# N-80 @ 7323' TD: 7325
Long St Cmt: 220 sx PBTD: 7265
Long St Date: 1/11/1986 (repair with patch @ 5210' in 2003)

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perfs 6918' - 7094'
Perforation Interval (2): Codell Perfs 7196' - 7212'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @ 7174' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6868', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 460'. Pump approx 175 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.