

## REENTRY PROCEDURE

**WELL NAME:** Badger Federal # 1 **DATE:** 10/21/2013  
**LOCATION:**  
Qtr/Qtr: SESE Section: 4 Township: 8N Range: 60W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-14372

**ENGINEER:** Ryan Olson 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** Re-enter and re-plug

**WELL DATA:** Surface Csg: 8 5/8" 24# set @ 624' KB Elevation: 4916'  
Surface Cmt: 350 sks GL Elevation: 4905'  
Long St Csg: NO PROD CSG TD: 7045'  
Long St Cmt: \_\_\_\_\_ PBDT: 7045'  
Long St Date: \_\_\_\_\_  
  
Plug Info (1) 50 sk cmt plug set @ 6900'  
Plug Info (2) 40 sk cmt plug set @ 3950'  
Plug Info (3) 30 sk cmt plug set @ 675'  
Plug Info (4) 15 sk cmt plug set @ 50'  
  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: Base Fox Hills @ 710', Deepest water well @ 360'

**WELL STATUS:** Well Abandoned 9/3/89  
**COMMENTS:** Remainder of hole filled w/ 10# mud. Sur csg cut off 4' below GL and plated welded on

### PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging.
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 6100'
- 15) TOOH with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 6050'.
- 17) RU cement crew and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement @ 6050'
- 18) POOH to 3000', RU cement crew and pump a balanced plug of 100 sks 15.8 ppg Class G "neat" cement @ 3000'
- 19) POOH to 860' (150' below Fox Hills Base @ 710')
- 20) RU cement crew and pump 356 sxs of 15.8ppg Class G "neat" cement bring cement to surface
- 21) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 22) Let cement set over night, verify cement has not settled and is still at surface. RDMO
- 23) Excavate around wellhead to 8' below grade, cut off 8 5/8" casing, weld on cap
- 24) Backfill hole and reclaim surface to original conditions