

WORKOVER PROCEDURE

WELL NAME: UPV 27-05G3 DATE: 11/20/2013

LOCATION: Qtr/Qtr: SWNW Section: 27 Township: 6N Range: 63W

COUNTY: WELD STATE: CO API #: 05-123-18780

ENGINEER: LEAH PERKINS 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# H-40 @ 473' KB Elevation: 4806 Surface Cmt: 200 sx GL Elevation: 4795 Long St Csg: 3 1/2" 7.7# M-75 @ 6964' TD: 6978 Long St Cmt: 100 sx PBTD: 6912 Long St Date: 1/28/1995

Plug Back (Sand or CIBP): RBP @ 6686' w/ sand plug on top Perforation Interval (1): Codell Perfs 6796' - 6816' Perforation Interval (2): Perforation Interval (3): Tubing: Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) RIH w/ workstring. Circulate sand plug @ 6676' and attempt to remove RBP @ 6686'. POOH. 3) RU WL. RIH w/CIBP. Set CIBP @ 6746', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug. 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 550'. Pump approx 210 sx shoe plug. Cement to surface. 7) RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.