

## WORKOVER PROCEDURE

**WELL NAME:** LILLI UNIT 03-15 **DATE:** 11/20/2013  
**LOCATION:**  
Qtr/Qtr: NENW Section: 15 Township: 8N Range: 58W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-14088

**ENGINEER:** LEAH PERKINS 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 176' KB Elevation: 4637  
Surface Cmt: 120 sx GL Elevation: 4628  
Long St Csg: 4 1/2" 11.60# @ 6339' TD: 6339  
Long St Cmt: 200 sx PBTD: 6324  
Long St Date: 10/15/1988

Plug Back (Sand or CIBP): **RBP @ 6147'**  
Perforation Interval (1): D Sand Perfs 6182' - 6188'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: **CBL on COGCC Website**

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Attempt to retrieve RBP @ 6147' and POOH.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6132', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 450'. Pump approx 175 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.